

## *Technical Bulletin Index* *Thermal*

<b>Number</b>	<b>Title</b>	<b>Date</b>
T-0038A	Introducing The New SL/T5R ES - How Do I Know It's An Energy Star?	05/10
T-0037A	Announcing the release of Printronix T4M CMB-MGL program file v1.14R, p/n 370768	04/10
T-0036C	Support for SAP Device Types YPTT4203 & YPTT4305 from Printronix	04/10
T-0035A	Announcing Support for Intelligent Mail Barcode (USPS 4-State Customer Barcode) on SL/T5000r and SL/T4M	04/09
T-0034A	Change in Available SL5000r/ SL5000e RFID Parts	11/08
T-0033A	Providing reliable Mark and Gap sensing for detecting notches or holes located within 0.250 inches from the left (inside) edge of media.	06/08
T-0032A	New RoHS compliant Online Data Validator (ODV) for SL5000e/T5000e and SL5000r/T5000r	11/06
T-0031B	T5000, T5000e, SL5000e, T5000r and SL5000r Special Key Press Combinations	04/10
T-0030A	Differences between the T5000e and the T5000r/PPC	04/05
T-0029A	Ribbon Motor Mounting Plate changes	03/05
T-0028A	Improving TOF Sensing for RFID SL5x04e & SL5x04r Printers	12/04
T-0027A	T5000 Vs. T5000e --- T5000e Changes and Differences From T5000	11/02
T-0026B	Release of Optional Media Cutter and Tray, Field Kits	10/00
T-0025B	Possible High Ambient Temperature Reset Problem	10/00
T-0024B	T5000 Printhead Compatibility/Usage	09/00
T-0023A	N/A	N/A

T-0022A	Low Holding Torque on Stepper Motor and Platen Moving After Changing The Stepper Motor or The Controller	07/00
T-0021A	Printer Emulation Protocol Switching Through PrintNet Adapter	06/99
T-0020A	SCO Unix OpenServer Printronix Setup Procedure	06/99
T-0019A	Unix System V Printing Setup Procedure	06/99
T-0018A	T3204 Twinax/Coax Installation & Ops Manual Typo	03/98
T-0017A	T3XXX Thermals Dip Switch Setting Clarification	03/98
T-0016A	T3XXX Reset and Self-Test Features Description	03/98
T-0015A	T3XXX Thermals with FGL F/W Getting 'Media Error'	03/98
T-0014A	T3306/T3308, New Printhead Home Position Sensor	03/98
T-0013A	T2204 Auto Label & Gap Sensing	03/98
T-0012A	T3306 and T3308 False 'Paper Out' Error with Parallel Port	03/98
T-0011A	T3204, T3306, T3308 Ribbon Wrinkle Troubleshooting Tips	03/98