

Printronic Technical Bulletin	Number 7-0013	Revision B
	Product Type P7000	Date 06/11
Subject: To Improve the Pedestal Lid Closure	Originator MB Tan	Page 1 of 2

Subject

To improve the Pedestal Lid closure.

Information

Follow the procedure below to improve the Lid closure on P7000 Pedestal model built before June 2011.

Procedure

- 1) Open the printer cover (Lid assembly).



- 2) Unscrew and remove the Strike Plate from the Lid assembly.



Strike plate

Printronic Technical Bulletin	Number 7-0013	Revision B
Subject To Improve the Pedestal Lid Closure		Page 2 of 2

3) Install the Washer 101526-002 as shown.



101526-002 Flat Washer

4) Install the Strike Plate back to the Cabinet Lid assembly.

Note: This procedure is only applicable if the lid of printer cannot be closed fully, especially when it is new.

Note: Washer Part Number is: 101526-002.
This washer is flat, steel, zinc coated blue, 0.149" x 0.367" x 0.030".